

SUBCONTRACTING NOTIFICATION

DATE: 5/2/2014

JOB DESCRIPTION:

The 832 perc return line was plumbed wrong when the line was installed. We did not notice the issue until the perc return control valve failed. We will schedule Greg in to correct the plumbing and replace the damaged part of the control valve.

CONTRACTOR: UPI

EXPECTED START DATE: 5/5/2014

EXPECTED FINISH DATE: 5/16/2014

REASON FOR USING SUBCONTRACTORS:

Certified welder required

PROJECT SUBMITTED BY: Carl Bustle

FORM GIVEN TO: *IBEW MAILBOX IN MAILROOM*

DATE: